

TOP SECRET

PRIORITY

OUT55785

1965 MAY 20 13 33Z

T O P S E C R E T 201325Z

PRIORITY [redacted] 4582

25X1

25X1

1

1. TELEMETRY OF MISSION 4017 REVEALS MALFUNCTION OF MIRROR IN AFT POSITION. USE FORWARD FRAMES ONLY FOR MEASUREMENTS.

2. ON MISSION 1019-1 ALL BINARY LIGHTS HAVE WORKED WITH FEW OBVIOUS EXCEPTIONS WHERE WHOLE BLOCK IS BLANK.

20 MAY 1965

T O P S E C R E T

--END OF MESSAGE--

COPIES RECEIVED <u>7</u>		
Cy No.	Office	Act.
<u>1</u>	File	
<u>2</u>	OS	<input checked="" type="checkbox"/>
	ADMIN	
	SEC BR	
	P&DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICB	
<u>3,4</u>	TID	
	PID	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	
<u>8</u>	[redacted]	

25X1

25X1

[redacted]

TOP SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

1